


Supplemental Shielded Z-MAX Module Instructions – OSP cable preparation

Alternate Step 1 cable prep for OSP shielded cable



* Refer back to Shielded Z-MAX Module Instructions 100.18077.00

2015 Siemon Rev. A Aug. 2015

Global Headquarters
Watertown, Connecticut USA
Tel: (1) 866-548-5814



For a complete listing of our global offices visit our web site